

**Source:** Leece-Neville Heavy Duty Systems Division  
**Bulletin No:** TSB-1212 **Date:** August 19, 2022  
**Models:** 4800 ign. excite  
**Subject:** Terminal Id. from 4800 to HAB alternators



techservice@prestolite.com

Various 4800 series ignition excite brush alternators can be replaced by BLD4000 series brushless alternators. See matrix below.


This document will help identify terminal location variances.

Note: Wire termination and routing will require changes.

Ignition lead used on existing 4800 series alternators are not required. Insulate this wire to prevent shorting and secure out of the way.

4800 series alternators listed on this document are grounded earth return where the BLD4000 series replacements are insulated return. Depending on the vehicle wiring a ground strap maybe required.

Model #	Voltage	Amperage	Substitute	Model #	Amperage
A0014861JB Sales: 4861JB	12	200	➔	BLD4026	220
A0014871JB Sales: 4871JB	12	270	➔	BLD4014	280
A0014872JB Sales: 4872JB	12	270			



**Important:** The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:

