

Source: Leece-Neville Heavy Duty Systems Division – Arcade, NY
Bulletin No: TSB-1210 **Date:** July 15, 2022
Models: 4800 J mount self-excite insulated return
Subject: Terminal ID from 4800 self-excite insulated to BLD4000




techservice@prestolite.com



Various 4800 series self-excite brush alternators can be replaced by BLD4000 series brushless alternators. See matrix below.

This document will help identify terminal location variances.

Note: Wire termination and routing will require changes.

Sense and lamp terminals are not required on BLD4000 series for operation.

Model #	Sales #	Voltage	Amperage	Substitute	Model #	Amperage
A0014818JB	4818JB	12	270		BLD4014	280



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

