

Source: Leece-Neville Heavy Duty Systems Division – Arcade, NY

Bulletin No: TSB-1200

Date: June 9, 2022

Models: A0014967PGH

techservice@prestolite.com

Subject: Terminal ID from A0014967PGH to BLP4009




Brush alternator A0014967PGH can be replaced by brushless alternator BLP4009.

This document will help identify terminal location variances.

Note: Wire termination and routing will require changes.

A0014967PGH is grounded earth return where the BLP4009 replacement alternator is insulated return. Depending on the vehicle wiring a ground strap may be required.

BLP4000 series alternators has a pad mount bracket that uses a short span (108mm) where the 4900 series uses a span of (126mm). Most engine brackets have the ability to accommodate both spans. Please verify your engine bracket and refer to TSB-1049 for more information.



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

