


Source:	Prestolite Electric Ltd - Greenford, London, UK
Date:	November 3, 2015
Bulletin No:	TSB4063 rev.1
Models:	M90R3538SE Starter motor
Subject:	PRODUCT CHANGE NOTICE

M90R3538SE STARTER BUILD CHANGE

To simplify our product offering and enable direct product replacement Prestolite have modified and released new starter motors for Volvo / Renault applications.


M90R3538SE will no longer be supplied with the earth lead to convert from 2 IGN terminal type to 1 IGN terminal type.

For 1 IGN terminal type use Prestolite part number M90R3556SE, replacing Mitsubishi M009T61471.



OE references:
5001866702, 7420732977, 7421036377
20397219, 85000148, 85006148
M009T61471, M009T61471AM
M9T61471, M9T61471AM

For 2 IGN terminal applications use M90R3538SE, replacing Mitsubishi M009T61473, M009T61474, M009T64791, M009T64972.



OE references:
7421598449, 7485013136
20563533, 20732977, 21025968,
21036377, 21598436, 21598446,
21598449, 85000934, 85000937,
85013134
M009T61472, M009T61473,
M009T61474, M009T64791,
M009T64971, M009T64972,
M9T61472, M9T61473, M9T61474,
M9T64791, M9T64971, M9T64972

This modification and range expansion offers direct like-for-like OE replacement.

For queries or assistance with correct product selection, please contact your Regional Sales Manager or alternatively contact the Technical Service Helpline on +44 (0) 1772 461776.

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at: