


Source: Leece-Neville Heavy Duty Systems Division -  
Arcade, NY USA  
Date: July 7, 2017  
Subject: Wiring Diagrams  
Bulletin No: TSB-1035  
Models: A0014991PA, A0014992PA Alternators

## Technical Service Bulletin

### 4991PA / 4992PA Wiring Diagram



**NOTE:** Load bearing cables (A) need to be the same length and wire size, and connected to a common point. This is needed to enhance the load sharing of each alternator.

**NOTE:** In order for system to work properly a 4991PA (Master) and 4992PA (Follower) must be used. Substituting a different alternator model will cause the system to not work properly.

This technical Service Bulletin is intended to be used along with TSB-1001 Recommended Wire Size Document.

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at: