

Source: Prestolite Leece-Neville Heavy Duty Systems
Bulletin No: TSB-1238 **Date:** January 8, 2024
Models: A0014861JB
Subject: Terminal identification to A0014868JGH




techservice@prestolite.com

Terminal identification to replace A0014861JB ignition excite alternator with A0014868JGH self-excite alternator.

! Ignition connection on A0014861JB is not required on A0014868JGH.
Insulate and secure this wire to prevent shorting, as it is not a necessary connection for the A0014868JGH.

A0014868JGH uses a shaft without a woodruff key. See TSB-1235 for more information.



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

