

Source:

Prestolite Leece-Neville Heavy Duty Systems

Bulletin No:

TSB-1245

Date:

June 20, 2024

Models:

AVI160

Subject:

Rectifiers A051520641S, A051106979S, A051106909S



techservice@prestolite.com

To all Prestolite Electric customers:

- ⚠

A change was made to how the regulator connects to the rectifier. Rectifiers A051520641S, A051106979S, A051106909S are designed to connect to R007521645S regulator.

To determine the correct service rectifier please refer to the list below.

Determine revision level of product.

See fig. 1




Fig 1

Revision Level

Model	Sales	Revision Level
AVI160J2004	A160204	H and higher
AVI160P2003	A160203	H and higher
AVI160J2008	A160208	H and higher
AVI160P2007	A160207	G and higher
AVI160J2011	A160211	E and higher
AVI160J2014	AVI2800J	E and higher
AVI160P2010	A160210	D and higher
AVI160P2012	AVI2800P	D and higher

Important:

The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Technical Service:

techservice@prestolite.com

