

Source: Leece-Neville Heavy Duty Systems Division – Arcade, NY


Bulletin No: TSB-1190 **Date:** July 27, 2021

Models: MS4-500

Subject: HM95 Upgrade




techservice@prestolite.com
+1 (844) 492-4062
+44 20 8231 1000



MS4-500 Rear View

MS4-500 Starter (Discontinued)



HM95 Rear View

The MS4-500 has been discontinued and in its place is the HM95R3804SEM

The “Switch” connection is now on the IMS Relay (Fig 1)

Torque specs for the connections are as follows:

Battery + : M10 X 1.75, 5-7Nm

Battery - : M10 X 1.75, 5-7Nm

Switch : M5 X 0.8, 1-2Nm

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

North & South America: Phone: +1 (844) 492-4062 | techservice@prestolite.com
Europe: Phone: +44 20 8231 1000 | techservice@prestolite.com

