


Source: Prestolite Electric Ltd - Greenford, London, UK  
Date: September 22, 2011  
Bulletin No: TSB4043 (Rev.01)  
Models: Alternator 66021590M  
Subject: Wiring instructions

### Replacement of 66021590 with 66021590M (Insulated return)

The 66021590 has been discontinued and replaced by the 66021590M. The "M" version is a marinised version of the older 66021590, and has the addition of a B- terminal which is insulated from the frame of the alternator. Therefore B- connection must be made from the alternator B- terminal to the battery or vehicle frame (if insulated return is not required). Please see diagram below:

B+ (Battery positive connection)  
B- (Battery negative connection)  
WL (Warning lamp connection)  
AC (Tacho connection)



**Important:** The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at: